




序号	报告编号	发布日期	结论	影像资料
1	GX-B1305/21-1-23003	2023/4/6	合格	
2	GX-B1500/21-1-23027	2023/4/6	所检项目合格	
3	GX-B1500/21-1-23028	2023/4/6	所检项目合格	

4	GX-B1500/21-1-23029	2023/4/6	所检项目合格		
5	GX-B1322/21-1-23071~23072	2023/4/4	所检项目合格		
6	GX-B1322/21-1-23073~23080	2023/4/4	所检项目合格		

7	GX-B1451/20-1-23161~23174	2023/4/6	所检项目合格	
8	GX-B1451/20-1-23175~23188	2023/4/4	所检项目合格	
9	GX-B1310/21-1-23027	2023/4/7	符合标准要求	

10	GX-B1310/21-1-23028	2023/4/7	符合标准要求	
11	GX-B1310/21-1-23029	2023/4/7	符合标准要求	
12	GX-B1427/21-1-23027	2023/4/7	符合标准要求	




13	GX-B1423/20-1-23120	2023/4/3	合格	
14	GX-B1423/20-1-23121	2023/4/3	合格	
15	GX-B1423/20-1-23122	2023/4/3	合格	

16	GX-B1423/20-1-23123	2023/4/3	合格	
17	GX-B1423/20-1-23124	2023/4/3	合格	
18	GX-B1423/20-1-23125	2023/4/3	合格	

19	GX-B1423/20-1-23126	2023/4/3	合格	
20	GX-B1313/21-1-23033~23034	2023/4/3	所检项目合格	
21	GX-B1423/20-1-23092	2023/4/4	综合判定：合格	

22	GX-B1423/20-1-23093	2023/4/4	综合判定：合格	 A photograph showing a red truck parked on a paved area. Three people wearing hard hats and work clothes are standing in front of the truck. The license plate is visible. A yellow timestamp '2023/4/4' is in the bottom right corner.
23	GX-B1423/20-1-23094	2023/4/4	综合判定：合格	 A photograph showing a green truck parked on a dirt or gravel surface. Two people wearing hard hats and work clothes are standing in front of the truck. A yellow timestamp '2023/4/4' is in the bottom right corner.
24	GX-B1423/20-1-23095	2023/4/4	综合判定：合格	 A photograph showing a green truck parked on a dirt or gravel surface. Two people wearing hard hats and work clothes are standing in front of the truck. A yellow timestamp '2023/4/4' is in the bottom right corner.

25	GX-B1423/20-1-23096	2023/4/4	综合判定：合格	 A black dump truck is parked on a dirt road. Two workers wearing hard hats and work clothes are standing in front of the truck. The truck has a large dump body. A yellow timestamp '2023-3-29' is visible in the bottom right corner of the photo.
26	GX-B1423/20-1-23097	2023/4/4	综合判定：合格	 A red dump truck is parked on a dirt road. Two workers wearing hard hats and work clothes are standing in front of the truck. The truck has a large dump body. A yellow timestamp '2023-3-27' is visible in the bottom right corner of the photo.
27	GX-B1423/20-1-23098	2023/4/4	综合判定：合格	 A red dump truck is parked on a dirt road. Two workers wearing hard hats and work clothes are standing in front of the truck. The truck has a large dump body. A yellow timestamp '2023-3-27' is visible in the bottom right corner of the photo.

28	GX-B1423/20-1-23099	2023/4/4	综合判定：合格	 A photograph showing a red truck with its cargo door open. Three workers in safety gear are standing around the truck. A yellow timestamp '2023/4/27' is visible in the bottom right corner.
29	GX-B1423/20-1-23100	2023/4/4	综合判定：合格	 A photograph showing a red truck with its cargo door open. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/4/27' is visible in the bottom right corner.
30	GX-B1423/20-1-23101	2023/4/4	综合判定：合格	 A photograph showing a green truck. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/4/27' is visible in the bottom right corner.

31	GX-B1423/20-1-23102	2023/4/4	综合判定：合格	
32	GX-B1423/20-1-23103	2023/4/4	综合判定：合格	
33	GX-B1423/20-1-23104	2023/4/4	综合判定：合格	

34	GX-B1423/20-1-23105	2023/4/4	综合判定：合格	
35	GX-B1423/20-1-23106	2023/4/4	综合判定：合格	
36	GX-B1423/20-1-23107	2023/4/4	综合判定：合格	

37	GX-B1423/20-1-23108	2023/4/4	综合判定：合格	 <p>2023/2/25</p>
38	GX-B1423/20-1-23109	2023/4/4	综合判定：合格	 <p>2023/2/25</p>
39	GX-B1423/20-1-23110	2023/4/4	综合判定：合格	 <p>2023/2/25</p>

40	GX-B1423/20-1-23111	2023/4/4	综合判定：合格	
41	GX-B1423/20-1-23112	2023/4/4	综合判定：合格	
42	GX-B1423/20-1-23113	2023/4/4	综合判定：合格	

43	GX-B1423/20-1-23114	2023/4/4	综合判定：合格	
44	GX-B1423/20-1-23118	2023/4/4	综合判定：合格	
45	GX-B1423/20-1-23119	2023/4/4	综合判定：合格	

46	GX-B1322/21-1-23071~23072	2023/4/4	本次共检验电力电缆2条，2条所检项目合格。	
47	GX-B1322/21-1-23073~23080	2023/4/4	本次共检验电力电缆8条，8条所检项目合格。	
48	GX-B1423/20-1-23127	2023/4/6	综合判定：合格	

49	GX-B1423/20-1-23128	2023/4/6	综合判定：合格	
50	GX-B1423/20-1-23129	2023/4/6	综合判定：合格	
51	GX-B1423/20-1-23130	2023/4/6	综合判定：合格	

52	GX-B1423/20-1-23131	2023/4/6	综合判定：合格	
53	GX-B1423/20-1-23132	2023/4/6	综合判定：合格	
54	GX-B1423/20-1-23133	2023/4/6	综合判定：合格	

55	GX-B1423/20-1-23134	2023/4/6	综合判定：合格	
56	GX-B1423/20-1-23135	2023/4/6	综合判定：合格	
57	GX-B1423/20-1-23136	2023/4/6	综合判定：合格	

58	GX-B1423/20-1-23137	2023/4/6	综合判定：合格	
59	GX-B1423/20-1-23138	2023/4/6	综合判定：合格	
60	GX-B1423/20-1-23139	2023/4/6	综合判定：合格	

61	GX-B1423/20-1-23140	2023/4/6	综合判定：合格	
62	GX-B1423/20-1-23141	2023/4/6	综合判定：合格	
63	GX-B1423/20-1-23142	2023/4/6	综合判定：合格	

64	GX-B1423/20-1-23143	2023/4/6	综合判定：合格	
65	GX-B1423/20-1-23144	2023/4/6	综合判定：合格	
66	GX-B1423/20-1-23145	2023/4/6	综合判定：合格	

67	GX-B1423/20-1-23146	2023/4/6	综合判定：合格	
68	GX-B1423/20-1-23147	2023/4/6	综合判定：合格	
69	GX-B1423/20-1-23148	2023/4/6	综合判定：合格	

70	GX-B1423/20-1-23149	2023/4/6	综合判定：合格	
71	GX-B1423/20-1-23150	2023/4/6	综合判定：合格	
72	GX-B1423/20-1-23151	2023/4/6	综合判定：合格	

73	GX-B1423/20-1-23152	2023/4/6	综合判定：合格	 A photograph of a red truck with a yellow license plate. Two workers wearing hard hats and work clothes are standing in front of the truck. The date '2023.03.21' is visible in the bottom right corner of the photo.
74	GX-B1423/20-1-23153	2023/4/6	综合判定：合格	 A photograph of a green truck with a yellow license plate. Two workers wearing hard hats and work clothes are standing in front of the truck. The date '2023.03.21' is visible in the bottom right corner of the photo.
75	GX-B1423/20-1-23154	2023/4/6	综合判定：合格	 A photograph of a green truck with a yellow license plate. Two workers wearing hard hats and work clothes are standing in front of the truck. The date '2023.03.21' is visible in the bottom right corner of the photo.

76	GX-B1423/20-1-23155	2023/4/6	综合判定：合格	
77	GX-B1350/21-1-23005	2023. 3. 30	所检项目合格	
78	GX-B1350/21-1-23006	2023. 3. 30	所检项目合格	

79	GX-B1350/21-1-23003	2023. 3. 30	所检项目合格			
80	GX-B1350/21-1-23004	2023. 3. 30	所检项目合格			
81	GX-B1351/21-1-23003-23006	2023. 3. 30	所检项目合格			

82	GX-B1359/21-1-23011-23026	2023. 4. 7	所检项目合格	 A worker wearing a black helmet and an orange high-visibility jacket is working on a piece of white equipment. The worker is looking at a laptop screen. A yellow timestamp '2023/2/21' is visible in the bottom right corner of the photo.
83	GX-B1359/21-1-23027-23038	2023. 4. 7	所检项目合格	 A worker wearing a black helmet and an orange high-visibility jacket is working on a piece of equipment. The worker is looking at a laptop screen. A yellow timestamp '2023/2/22' is visible in the bottom right corner of the photo.
84	GX-B1359/21-1-23039-23046	2023. 4. 7	所检项目合格	 A worker wearing a black helmet and a blue high-visibility jacket is working on a piece of equipment. The worker is looking at a laptop screen. A yellow timestamp '2023/2/21' is visible in the bottom right corner of the photo.

85	GX-B1359/21-1-23047-23059	2023. 4. 7	所检项目合格	
86	GX-B1352/21-1-23045-23069	2023. 4. 7	所检项目合格	
87	GX-B1352/21-1-23070-23090	2023. 4. 7	所检项目合格	

88	GX-B1352/21-1-23001-23020	2023. 4. 7	所检项目合格	
89	GX-B1352/21-1-23021-23044	2023. 4. 7	所检项目合格	
90	GX-B1352/21-1-235009-235016	2023. 4. 7	所检项目合格	

91	GX-B1352/21-1-235001-235008	2023. 4. 7	所检项目合格			
----	-----------------------------	------------	--------	--	---	--